

INSTALLATION INSTRUCTION FOR FIXTURE 1731

WARNING! SHUT OFF THE POWER AT FUSE OR CIRCUIT BREAKER.

ASSEMBLY THE FIXTURE(Fig.1)

1. Carefully unpack your new fixture and lay out all the parts on a clear area. Take care not to lose any small parts necessary for installation.
2. Thread the support rods (G) together tightly;
3. Screw the bottom end of the support rods (G) onto the nipple (H) tightly, and thread the top end of support rods (G) into the swivel (F) properly, and tighten with the thumb screw on the swivel (F);
4. Put the Glass Shade (J) over the socket (I) well, and secure with socket ring (K);

MOUNTING THE FIXTURE

1. Shut off the power supply at the fuse box or circuit breaker box. Remove the old fixture from ceiling. Including the cross bar.
2. Thread the mounting screws (B) properly into the pre-drilled mounting holes on the Cross Bar (A), then attach the cross bar(A) onto the outlet box using the outlet box screws(C), the side of the cross bar(A) marked with "GND" must be faced out.
3. Follow the wire wiring instructions carefully(See Fig.2).
4. Lift up the canopy (D) over the outlet box, and let mounting screws(B) protrude the pre-drilled mounting holes on the Canopy (D), then secure with Ball nut(E) tightly.
5. Install the light bulb in accordance with fixture's specifications. DO NOT EXCEED THE MAXMUM WATTAGE RATING!

Wiring (See fig.2)

1. Connect the electrical wires as follows. Connect the black wire from the fixture to the black (HOT) house wire. Connect the white wire from the fixture to the white (Neutral) house wire. Make sure all the wire nut was secured. You may wrap the connections with electrical tape. If your outlet box has a ground wire (Green or Bare Copper) connect fixture's ground wire to it. Other wise attach the bare copper fixture wire to the green ground screw on the cross bar.
2. Tuck the wire connections neatly into the ceiling junction box.

Fig.1





Fig.2



UL
Listed

american
lighting
association